

Application Guide

ReTac Clear PET

For Windows



Smooth Surfaces



Tools Required



Dry Application



Easy Application

Please Read Carefully

Make sure you understand all guidelines before applying the graphic.

Test a small sample on the intended surface for at least 48 hours to ensure compatibility.

For large/multi-panel graphics, use experienced installers.

You must independently determine the suitability of this product for your intended application.

Tools Recommended

Lint-free cloths

Cleaning solution or wipes

Window scraper

Soft edge squeegee

Suitable Surfaces

Glass

Walls

Smooth, flat surfaces

Unsuitable Surfaces and Paints

Textured surfaces

Chalky or sandy substrates

Wipeable paints

Acrylic / Perspex

Surface Preparation

- Remove dust and dirt with a lint-free cloth.
- Ensure the glass is smooth, clean, and dry.
- Any debris can prevent proper adhesive flow and cause air pockets.

Applying the Graphic

1. Acclimatize the graphic by unrolling it on a clean, flat surface.
2. Measure and mark the area for application using measuring tools and masking tape.
3. Peel back the release liner about 4 inches, exposing the adhesive.
4. Position the graphic and press the adhesive onto the surface.
5. Begin from the top edge, using firm, overlapping strokes with a squeegee from the center outwards.
6. Continue to remove the liner and apply the graphic in 8-inch increments.
7. Apply enough pressure for a strong bond between the adhesive and substrate.
8. Any bubbles can be removed by lifting the graphic and reapplying.
9. Give the edges an additional squeegee to ensure good adhesion and avoid lifting.

Other Considerations

- Water is not required for the graphic application; using water may result in failure of the adhesive.
- Never apply a graphic below the minimum application temperature.
- ReTac products are designed for clean and easy removal, though results may vary depending on the substrate and preparation. A test is always recommended.
- For larger and more complex graphics, an experienced applicator/installer is recommended.

DRYTAC[®]
ADHESIVE SCIENCE

www.drytac.com